

NO LIGHTS.
HEAT: STOVE
POWER: STEAM
FUEL: COAL.
NO FIRE APPS.
Foundry.
Mach. Shop.
Confec. Rest.
Barber.
Paint Shop
DRS OFF.
Sal.
B & S. & Hats.
OLD LEHIGH SLATE CO
NO WATCHMAN.
NO LIGHTS.
HEAT: STOVE
POWER: STEAM.
FUEL: COAL.
SMALL F.P. & 100' 3/4" HOSE
Slate Saw'g & Polishing: Framing 2".
Finishg.
IR. CH. 40'
W. TANK.
Finishg.
Wheel Wright.
818 1/2
815 1/2
817 1/2
819 1/2